

Enhancing nuclear safety

French requirements for the design, manufacture and use of bolts and screws equipping packages for the transport and storage of radioactive material

A. Carcreff¹, B. Eckert¹, M. Moutarde¹, B. Monnot¹, D. Hamoniaux², C. Moniez-Perrin², T. Grunenwald², T. Delon³, M. Santini⁴, M. Lemoine⁵, S. Nallet⁵, A-C. Jouve¹

IRSN (Radioprotection and Nuclear Safety Institute), France
French Nuclear Safety Authority for Defense Activities (ASND), France
French Alternative Energies and Atomic Energy Commission (CEA), Cadarache, France
French Alternative Energies and Atomic Energy Commission (CEA), Le Barp, France
ORANO TN, France

PATRAM 2019 Thursday, August 8, 2019



MEMBER OF ETSON Copyright IRSN.

Summary

- 1. Context of the working group
- 2. Design criteria
- 3. Events declared in France
 - Self-loosening of impact limiters screws
 - Screws do not comply with the PDSR
 - Hydrogen embrittlement
 - Lubrication of the screws





Context of the working group

Participants





Main objectives:

- Specify requirements in order to improve the safety level
- Provide a technical support by writing a handbook
- Better understanding of the safety issues
- Reducing the assessment duration and improving the information exchange



Handbook is divided in 4 chapters

1) Design and modeling

- 2) Representativeness of screw assemblies during drop test
- 3) Manufacturing process
- 4) Exploitation









Lpackage

Safety functions

Ensure the integrity of the package design safety functions

 Containment (lid closure system): gaskets must have a sufficient compression ratio in all conditions of transport

Criticality safety: prevent the water penetration in the package cavity

- Mechanical behavior (impact limiters) :
 - $\checkmark~$ absorb mechanical energy in case of impact
 - \checkmark ensure a thermal protection of the containment system gaskets



Thermal behavior

5



Design Criteria

Recommendations

 Containment screw assemblies have to stay in their elastic behaviour in all conditions of transport



Elastic behaviour



Plastic behaviour

- Pre-load can't be exceeded in routine conditions of transport
- No plastic strain allowed in normal conditions of transport



Self-loosening of package impact limiters screws

- 25 events declared in France during the last 7 years
- Hypothesis and observations:
- Heavy type B packages (spent fuel for most events)
- Large impact limiters with few screws
- Large diameter screws
- > Dynamic transverse loads are more likely to generate a screw self-loosening
 - Self-loosening solutions:



Serrated washer



Grower washer



Nord-lock washer



These solutions may degrade the bearing surface !





Self-loosening of package impact limiter screws

Recommendations

- Apply a sufficient pre-load in the screws
- Guaranty the cleanliness of screws and the threads (visual control, storage in clean spaces, anti-dust plug on the screw holes)
- Tightening operations:
 - ✓ respect the tightening order
 - ✓ respect the waiting period until the thermal steady state
 - ✓ check of the screw tightening by another operator with a different wrench







Recognition of the screws

- One event declared in France in 2015:
 - ✓ impact limiters screws didn't comply with the safety report
 - ✓ same diameter but the length was different
- Screws can be confused when they have similar characteristics

Recommendations

- screw marking
- method for identifying screws:
 - color code to associate the screws to the components to fix
 - ✓ storage racks







Hydrogen Embrittlement Failure

During tightening, some failure of high quality class screws occurred

- Internal Hydrogen Embrittlement (IHE):
- residual hydrogen from processing steps such as pickling and



Property class screws ≥ 10.9 are susceptible to hydrogen (Vickers hardness ≥ 360 HV)



Hydrogen Embrittlement Failure

Recommendations

- Acid pickling for property class screws > 10.9 is not recommended
- When the screw is coated by an electroplating process:

Property class	≤ 9.8	10.9	12.9
Vickers Hardness	< 360 HV	360 HV ≤ Hardness ≤ 390 HV	> 390 HV
Specifications	Additional verification of the manufactural process or hydrogen embrittlement test methods AND No necessary baking	Additional verification of the manufactural process or hydrogen embrittlement test methods OR Baking	Additional verification of the manufactural process or hydrogen embrittlement test methods AND Baking

Baking is a low temperature heat treatment allowing extract hydrogen



Hydrogen Embrittlement Failure

Zinc lamellar coatings

- Zinc lamellar coatings are :
 - > not concerned by hydrogen embrittlement
 - > non-electrolytically applied
- Mixture of zinc and aluminium flakes, which are bonded together





Zn coating

Quality class screws ≥ 14.9 is not recommended



Lubrication of the screws



 When lubricant is required only on thread, it may be applied involuntarily under head (even if it's forbidden !)



increase the stress in the screw







Lubrication of the screws

Recommendations

14

- If lubrication is necessary, apply lubricant on the threads and under the screw head
- Lubricant must be consistent with the friction coefficients used in the design calculations
- Guarantee the friction coefficient:
 - number of tightening/untightening
 - periodicity for screws replacement



TN 24 DH Packages Doel (Belgium)



Conclusion

- Recommendations included in a dedicated guidance established thanks to the French nuclear authorithy for defense activities
- Positive feedback from the collaboration between safety authority, TSO and applicants
- Some topics are not yet fully know:
 - self-loosening of the impact limiters screws
 - brittle fracture

Some additional requirements may be added in a future review of the handbook



Thank you for your attention

For more information, please contact:

alan.carcreff@irsn.fr

French requirements for the design, manufacture and use of bolts and screws equipping packages for the transport and storage of radioactive material - *Copyright IRSN*.



16