

Micro-climatic monitoring to optimize ageing test methodology:

Application on the Saint-Remi Basilica (Rheims, France)

E. HUBY, C. THOMACHOT-SCHNEIDER, P. VAZQUEZ, G. FRONTEAUGEGENAA EA 3795, URCA, France












EGU 2019 - 10/04/2019




EGU 2019 - 10/04/2019





Areas exposed to solar radiation





Areas exposed to solar radiation














INTRODUCTION




Standard test procedure





NF EN 12371 Natural stone test methods Determination of frost resistance



IN SITU MONITORING

Saint-Remi Basilica: inscribed on UNESCO's World Heritage List



Aerian view of the Saint-Remi Basilica



Localization of Rheims

Two types of limestone:

"Courville"

Lutetian limestone Original stone



Courville Gx20

"Savonnières"

Jurassic limestone Restoration stone




Savonnières Gx20



Picture of weathered stones and restored stones on the Basilica.

Monitoring: network of 15 sensors



Different **heights**:


25m and 30m.

Different orientations:


North, South, East and West.


Monthly average







Monthly average






Daily average








Daily average of relative humidity on the 2nd floor of the south tower





Daily values – time step of 1 hour.



















Identification of typical events: "Rainy day"




EGU 2019 - 10/04/2019 22


RH




Identification of typical events: "Frost day"




Repartition of typical days for the different orientations




Repartition of typical days for the different orientations




	Temperature variation	Heating/Cooling rate	Humidity
Sunny day	20 – 35°C	0,2 °C/min	Dry



	Temperature variation	Heating/Cooling rate	Humidity
Sunny day	20 – 35°C	0,2 °C/min	Dry
Rainy day	20 – 35°C	0,2 °C/min	1h imbibition



	Temperature variation	Heating/Cooling rate	Humidity
Sunny day	20 – 35°C	0,2 °C/min	Dry
Rainy day	20 – 35°C	0,2 °C/min	1h imbibition
Frost day	-10 – 5°C	0,15 °C/min	1h imbibition




Identification of typical events

1 day observation – time step of 2 minutes.



Façades orientation of the Basilica (Google Earth view,




Identification of typical events


1 day observation – time step of 1 hour.



Façades orientation of the Basilica (Google Earth view)




	Temperature variation	Heating/Cooling rate	Humidity
Sunny day	20 – 35°C	0,2 °C/min	Dry
Rainy day	20 – 35°C	0,2 °C/min	1h imbibition
Frost day	-10 – 5°C	0,15 °C/min	1h imbibition day
Short variations	20 – 25°C	1 °C/min	Dry



AGEING TESTS


Simulation of a vertical surface exposed to temperature variations






AGEING TESTS


Simulation of a vertical surface exposed to rain



Setting




Sample preparation.




Experimental setup.

Introduction **Ageing tests** Conclusion In situ monitoring

Savonnières – Sunny day











- Plate — 8cm - 1,3cm — 7cm - 0,2cm
- 7cm 2,6cm
- 6cm 1,3cm 5cm 0,3cm 5cm 2,7cm


Savonnières – Sunny day













— 5cm - 2,7cm

Savonnières – Sunny day








Plate 8cm - 1,3cm 7cm - 0,2cm


7cm - 2,6cm 6cm - 1,3cm

– 5cm - 0,3cm


— 5cm - 2,7cm

38 EGU 2019 - 10/04/2019

Ageing tests: Courville – Sunny day










- Plate — 8cm - 1,3cm ___ 7cm - 0,2cm
- 7cm 2,6cm
- 6cm 1,3cm 5cm 0,3cm 5cm 2,7cm

Ageing tests: Courville – Sunny day










— 7cm - 0,2cm — 7cm - 2,6cm — 6cm - 1,3cm — 5cm - 0,3cm

– 5cm - 2*,*7cm

Ageing tests: Courville – Sunny day



Results – Sunny day




Courville 1 cycle 5.10⁻⁵ 15 cycles 2.10⁻⁵



Savonnières 1 cycle 2.10⁻⁴

Picture of weathered stones and restored stones on the Basilica (West Façade).




EGU 2019 - 10/04/2019

Results – Sunny day




Courville 1 cycle 5.10⁻⁵ 15 cycles 2.10⁻⁵



1,0 mm

Savonnières 1 cycle 2.10⁻⁴




Picture of weathered stones and restored stones on the Basilica (West Façade).



On façades exposed to the sun: more thermal fatigue on Courville limestone.


CONCLUSION



EGU 2019 - 10/04/2019

44


CONCLUSION





PERSPECTIVES

- Ageing tests simulating frost days according to the in situ monitoring
- Mechanical properties & global dilatation measurements
- More intense ageing tests
- Study of a restoration mortar (Lithomex)



Thank you for your attention







