



# 10 years of thermo-mechanical monitoring of rock columns – *les chandelles de l'Escalette*, France

**M. Gasc-Barbier<sup>1</sup>, V. Merrien-Soukatchoff<sup>2</sup>, JL Genois<sup>1</sup>,  
C. Mougins<sup>1</sup>, P. Azémard<sup>1</sup>**


<sup>1</sup>Cerema, Aix-en-Provence, France

<sup>2</sup>Cnam, Paris, France

# Plan

- Site localisation
- Recordings
- Mechanical Interpretation
- Conclusion and perspectives

# Site



# Site - description




# Site - sensors



# Recording (temperature)


Weekly average







# Recording (displacements)


## Weekly average



# Displacement vs temperature



# Displacement vs temperature



Sensor	Annual displacements range (mm)	annual hysteresis (mm)	6-years drift (mm)
H1	- 2.25	0.3	-1.4
B2	- 2	0.3 to 0.4	- 0.8 to -1
H3	-2.5	2	-2.5 to 3
B4	-2.5	0.5	-1.1 to -1.5
H5	0.95	0.5	0.5 to 0.6
B6	1.7	0.3	2
H7	-0.5	0.35	-0.9 to -0.95
B8	1.1	1.1	4 to 5.5
H9	2.1	1.3	1.5
B10	2.5	1.55	1.3 to 1.5

# Mechanical interpretation



# Conclusion and perspectives

- It is more than “just” a mechanical interpretation
- Data processing is still under study
- ...